

9.69 347-NOR, 356-CP, 392-D/L, 1222-D/L, 1308-CF, 1311-CR, 1313-CF, 1319-KN,
1336-KN, 1346-MN, 1416-HD, 1503-CR, 1504-CR, 2015-KN, 2343-CN, 2363-D/L,
2368-CY, 2404-BN, 2420-CF, 2421-HH, 2424-BN, 2485-BN, 2488-KN, 2494-BD.

2792-BN, 3000-MN, 3001-BE, 3004-BE.

10.69 332-D/L, 334-D/L, 341-D/L, 343-D/L, 344-D/L, 347-CF, 348-D/L, 351-D/L,
356-D/L, 357-D/L, 358-D/L, 362-D/L, 363-D/L, 367-D/L, 381-CF, 387-D/L,
388-D/L, 389-D/L, 393-D/L, 401-D/L, 501-D/L, 504-D/L, 505-D/L, 1222-CY,
1232-D/L, 1234-D/L, 1324-HD, 1334-BN, 1339-D/L, 1341-D/L, 1342-BN,
1400-D/L, 1410-D/L, 1432-D/L, 1603-CY, 2353-KN, 2357-SD, 2378-D/L,
2379-D/L, 2380-D/L, 2382-D/L, 2383-D/L, 2384-D/L, 2386-D/L, 2474-D/L,
2528-CN, 2613-D/L, 3002-BE.

1603 at Canvey is for operation on service X10.

3003 was temporarily allocated to Braintree but has now returned to Clacton and has been replaced at Braintree by 3002.

Service Revisions

The following service revisions have recently been applied for:

- 26 Temporary terminal in Romford to be Ring Road, L.T. Bus Stop.
112 Revised terminal in Holland-on-Sea to be Canterbury Road.
123,207) 5 day anywhere tickets issued by Eastern Counties Omnibus Co.Ltd.
212) to be available for use on these jointly operated services.
307,308 Revised terminal in Saffron Walden to be Castle Street.
308 To be extended from Langley Lower Green to Langley Upper Green.

General

The Bristol VRT's are at present employed on the following services, all the vehicles are operating O.M.O.

3000	(MN)	Services 19/19A
3001	(BE)	Service 321
3002	(BE)	Service 321
3003	(CN)	Service 111
3004	(BE)	Service 321

TILLINGS TRAVEL LTD.

Withdrawn Vehicle

9.69 T314(617 JPU)

This was the last Bristol LS coach in the fleet. Although withdrawn the vehicle is still pending disposal.

Fleet Changes

9.69 NIL

10.69 Delicensed: T540/2.

(We are indebted to I. R. Kydd Esq., Chief Engineer, Eastern National Omnibus Co. Ltd. for much of the information in this news sheet)

SOUTHERN CORPORATION

General

Albion Lowlander 331(7095 HJ) has been equipped for, and has been observed operating, O.M.O.

Corrections to fleet list

The following corrections to fleet list E.P.2 should be noted:

287 - 298 (LEJ 389 - 400) are of chassis type PD2/12
299 - 304 (MHJ 921 - 926) are of chassis type PD2/20
305 - 310 (OHJ 75 - 80) are of chassis type PD2/40